

STORM WATER PUMP STATION FACILITY IMPROVEMENTS

Public Works Commission
10/20/2021

John Martin
Contract Administrator

STORM WATER PUMP STATIONS – CURRENT CONDITION



- ▶ Station louvers (left photo and above left) are wooden, original, and deteriorating. They will be upgraded to coated steel to improve durability and sound attenuation.
- ▶ Some station doors are thin corrugated metal (above right). These present a security risk and will be replaced with heavy gage steel doors.



- ▶ Station roofs are nearly 30 years old and require replacement. Roof leaks have been reported at some stations.
- ▶ Fascia boards are deteriorated and will also be replaced and coated.