



ASCON LANDFILL SITE UPDATE

CURRENT UPDATES

- CLEAN-UP EFFORTS HAVE STOPPED.
- ASCON IS PURSUING TENTING/ENCLOSURE PERMITS AND WORK PLAN APPROVAL.
- HAMILTON BERM SLOPE CRACK EVALUATION AND PROPOSED ACTIONS.

SLOPE FAILURE CONCERN

DTSC & ASCON HAVE EVALUATED TENSION CRACKS ON THE NORTHWEST BERM

- December 31st ASCON Identified Tension Cracks on the Berm along Hamilton.
- February 6, 2020 additional Tension Cracks identified on the Berm
- DTSC has estimated a Medium to High Risk of Slope Failure.
- DTSC and ASCON have evaluated options to repair and alleviate slope failure.

Ascon Landfill Site Slope Inspection NW Berm Geotechnical Observations on Dec 31, 2019



TENSION CRACKS IDENTIFIED



TENSION CRACKS IDENTIFIED



SLOPE FAILURE CONCERN

DTSC & ASCON HAVE EVALUATED TENSION CRACKS ON THE NORTHWEST BERM

- DTSC held a public Online presentation/discussion on April 2, 2020.
- DTSC Recommended Managed Controlled excavation
- DTSC answers to the questions posed at the meeting is anticipated this week.
- Planned action determination is anticipated by the end of the Week.

SLOPE FAILURE CONCERN

DTSC & ASCON HAVE BERM

- DTSC held a
- DTSC Recom
 - Managing
 - Utilize Odo
- DTSC answer
- week.
- Planned acti



The flyer features the DTSC logo on the left, which includes a stylized sun and water waves. The main text is centered and reads: 'Community Forum Berm Mitigation at Ascon Landfill', 'April 2, 2020', and '1:30 p.m. to 3:30 p.m.'. Below this, it states 'SITE MITIGATION AND RESTORATION PROGRAM' and 'DEPARTMENT OF TOXIC SUBSTANCES CONTROL (DTSC)'. The bottom half of the flyer shows a photograph of a lush green forest with sunlight filtering through the trees. A small footer at the bottom right says 'This folder is up to date.'

and this
week.

SLOPE FAILURE CONCERN

DTSC & ASCON HAVE EVALUATED TENSION CRACKS ON THE NORTHWEST BERM

- DTSC Recommended Managed Controlled excavation
 - Dramatically limit daily excavation rate.
 - Utilize Multiple Odor Controls (foam, soil, and plastic covering).
 - Real-time dust and odor monitoring
 - Close down excavation if odors cannot be controlled
 - DTSC Staff on-site when work is conducted

SLOPE FAILURE CONCERN

DTSC & ASCON FUTURE CONSIDERATIONS

- DTSC held a public Online presentation/discussion on April 2, 2020.
- DTSC Recommended Managed Controlled excavation
- DTSC answers to the questions posed at the meeting is anticipated this week.
- DTSC anticipated to provide final determination by the end of this Week.

For More Information on Ascon Project

- **Contact:** Safouh Sayed, DTSC Project Manager
Safouh.Sayed@dtsc.ca.gov
(714) 484-5478

- **DTSC website:**

<https://dtsc.ca.gov/smrp-projects/ascon-landfill-site/>

- **DTSC EnviroStor:**

https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=30490018



ATE



ASCON LANDFILL SITE UPDATE

HOW TO FIND OUT MORE INFORMATION:

- [HTTPS://ASCONHB.COM/](https://asconhb.com/)
- SIGN-UP FOR EMAIL UPDATES ON THE WEB PAGE.
- PUBLIC HOTLINE FOR NON-EMERGENCY INFORMATION: (714) 388-1825